Job Photo Closeout Report

Maplewood Apt 3B

Work order number: WO-2026-418

Unit address: 418 Maplewood Lane, Unit 3B

Invoice reference: INV-418

Contractor: Juniper Repair Co.

Contractor contact: crew@example.test

Prepared date: 2026-04-22

Completed: 3 / Open or blocked: 1

General completion documentation based on user-entered statuses. Confirm site conditions and acceptance separately.

WO-01 / Replace vanity faucet

WO-2026-418 / Hall bath / Completed

Before



After



Notes

Installed the new faucet and checked for leaks.

WO-02 / Patch and touch up wall

WO-2026-418 / Bedroom / Completed

Before



After

No photo provided

Notes

Patch was sanded and painted.

WO-03 / Adjust entry door latch

WO-2026-418 / Entry / Open

Before



After



Notes

Return visit scheduled to check latch alignment.

WO-04 / Seal and repaint window sill

WO-2026-418 / Living room / Completed

Before



After



Notes

Caulk cured and sill received two coats.